

CLASS 'N
 No: N15-3

RECORDER: _____

MICS: _____

Ext. batt ☐ Phantom ☐ Socks ☐

TAPE 207 @ _____ IPS

TRACK: Full ☐ 1/4 ☐ Other ☐

STEREO ☐ MONO ☐ QUAD ☐

TEMPERATURE: _____ °F

HUMIDITY: _____ %

WIND: 3 MPH from N

OTHER: light met snow falling

PLACE RAIL B-C

DATE NOV 15/73 TIME 10:20 AM (PM)

(NEAR) _____ MIC SETUP _____ (FAR)

MIC. DISTANCE _____ Ft. _____ Ft.

LEFT POT _____ RIGHT POT _____

REMARKS	TIME
	00
	01
	02
	03
	04
	05
	06
	07
	08
	09
	10
	11
	12
	13
	14
	15
	16
	17
	18
	19
	20
	21
	22
	23
	24
	25
	26
	27
	28
	29
	30

10" 20" 30" 40" 50" Less 90

2 7 AM. Shift whistle; Trail Smelter -
 extended in parking lot at foot of
 Smelter steps. 200 yds from whistle.
 Raining, No wind, Temp 35° F

3 false (crumby directions) false start

3 TRAIL SMELTER ~~to~~ Zinc Melting Room
 Pts 95

8:10 AM, going into Zinc Tank Room

86A - 99 Clark at 25'

Shipping 88A at 10' 92C

more sand 88A

87A piling poles at 15-20'

93A little at 10'

Clark 89 at 35'

84A where air con at 40'

86A at 15' air crane

100 A + dumping at 15'

102 A / 109 C at 15' from wheel dropping on big pipe 10' in diam

105

100 A / 104 C - 105 C

101 A / 110 C

at 8' 970

at Zinc ~~slabs~~ slabs

dropping from ceiling wheel

Cintara Plant

Cintara Plant

102 A / 107 C at 35' 40' from knot

REEL # DETAILS

1 Columbia River & CMXS Co.
 (Cominco) Smelter from
 Gyro Park (near Sandy Island)
 temp 32-34° F, time 10:20 PM
 distance 80-100 yds to
 river - & 1/4 mi to smelter
 wires posted w/ cross wires
 at smelter to left across river.

51-55A 59-63 A
 60-66 C 68-74 C

cal = -4
 in there
 reading

⑧ 97A/104C
knocking
96A pshs
40 behind

⑨ 90A/102A
ambience
burns off side
at 12 from
under steel
wall.

⑩ 86-92 A/99-14C
at 120-~~120~~ 130'

CLASS 'N ML 6 ①
 No: 1
 RECORDER: _____
 MICS: _____
 Ext. batt ☐ Phantom ☐ Socks ☐
 TAPE 207 @ _____ IPS
 TRACK: Full ☐ 1/4 ☐ Other ☐
 STEREO ☐ MONO ☐ QUAD ☐
 TEMPERATURE: 54 °F
 HUMIDITY: _____ %
 WIND: _____ MPH from _____
 OTHER: _____

PLACE TRAIL SNE (PR)
 DATE Nov 16/73 TIME 8:30 AM
 (NEAR) _____ MIC SETUP _____ (FAR) _____
 MIC. DISTANCE _____ Ft. _____ Ft. A
 LEFT POT _____ RIGHT POT _____

		10"	20"	30"	40"	50"
	REMARKS					
00						
01	100 A at 30' and				89 A at 20'	
02	at 30'				96 C rumble ambience	
03						
04	6					
05						
06						
07						
08	Amigos					
09	at Bullion					
10						
11	95 A } at 40'					
12	94 C					
13	banes					
14						
15	9					
16	Back					
17	mic's acting up					
18	pts 100					
19	next to timer					
20						
21	78/19A/9D-104 C ambience					
22	pop's - up to 90 A/86A					
23						
24	10					
25						
26	11					
27	up top tanks					
28	pts 100					
29	87 A at 35'					
30	Men working with power					

REEL # 1 DETAILS 3 full shift

① ~~1~~ ~~4~~
 GINTERING
 PLANT
 See ⑩ on map
 N15 - ③ for levels
 at 130' - 140'
 Pts 100
 Monotail in
 DX L's

④ Melting pots
 too hot no
 will 3
 where 97 A at
 8'
 88 A chunk at
 100'
 91-94 C came
 at 8' with
 molten lead pots
 98-102 A
 long at 35'

THIS ONE WILL
 BE LOW -
 let ex jump in
 100.0 SW
 85 A at 20'
 92 A at 12'
 88 A
 90 A at 35'
 Lead Runway - next
 to construction
 ambience 97-99A
 84-86 C
 at 215-20'
 and a rotating wheel
 knocking
 82 A / 88 C
 at 140'
 - 35° F

